

## STATE OF WASHINGTON

## DEPARTMENT OF ECOLOGY

P.O. Box 47775 • Olympia, Washington 98504-7775 • (360) 407-6300

June 12, 2000

Bill & Donna Bourland 8818 3<sup>rd</sup> Avenue SE Everett WA 98208

Re: Water Right Application for No. G2-29916

This letter is to acknowledge that the Washington State Department of Ecology received your water right application. We have assigned your application the number indicated above. Please include this number in future correspondence regarding your application with the Department of Ecology.

When we begin actively evaluating applications in your area, we will prepare a public notice and send it to you with publication instructions. It will be sometime before we are able to begin working in your area. In the meantime, please notify Ecology of changes such as address, property ownership, or variations in your proposed water use plans.

The availability of water in Washington state is a serious problem. Much of the water in our state has already been appropriated. The competition for water has escalated with our state's increasing population, conflicting water policy issues, and grave declines in salmon and other fish populations. A new watershed management law brings us a step closer to addressing some of these issues. It sets into motion a locally based process to address water quantity, quality, and habitat issues. Watershed management will help meet challenges for getting water to people, industries, farms, and fish.

In some areas of the state, we are continuing to evaluate applications within watersheds where we have previously gathered information and completed watershed assessments. We are also continuing to process water right permit or change applications that are intended to address public health and safety emergencies, the natural environment, or are for nonconsumptive withdrawals. All other applications are grouped by watershed and processed according to the date of submittal, and when we have enough information and staff resources to make decisions.

If you would like further information on your application, please contact the Southwest Regional Office at (360) 407-0240.


200 E 100 18


Sincerely,


J. Mike Harris


J. Mike Harris Water Resources Supervisor Southwest Regional Office


JMH:th











## WELL REPORT WATER

STATE OF WASHINGTON

Start Card No. 11 Unique Well I.D. # AFA397 Water Right Permit No.

OWNER: Name BOURLAND, BILL Address NEAR 97 HEATHER PARK PORT ANGELES, WA 98362-(1) OWNER: Name BOURLAND, BILL R: Name BOUKLAND, BILL AUGUESS NEAR 7, HERTHER TAKE 1/4 NW 1/4 Sec 3 T 29 N., R 6 (2) LOCATION OF WELL: County CLALLAM - NE 1/4 NW 1 (2a) STREET ADDRESS OF WELL (or nearest address) NEAR 97 HEATHER PARK, PORT ANGELES (3) PROPOSED USE: DOMESTIC (10) WELL LOG \_\_\_\_\_\_ (4) TYPE OF WORK: Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change in formation. Owner's Number of well (If more than one) Method: ROTARY NEW WELL Diameter of well 6 inches
Depth of completed well 101 ft. (5) DIMENSIONS: T0 Drilled 101 ft. MATERIAL FROM TOP SOIL
BROWN CLAY AND COBBLES
GRAY CLAY AND COBBLES
BROWN SAND & GRAVEL
BROWN WB SAND & GRAVEL 0 (6) CONSTRUCTION DETAILS: Casing installed: 6 ----<del>-</del> 18 Dia. from 0
Dia. from
Dia. from Casing ins ft. to 101 ft. to ft. to 18 48 ft. ft. 48 91 Perforations: NO
Type of perforator used
SIZE of perforations
perforations from
perforations from
perforations from
perforations from in. by in. ft. to ft. to ft. to Screens: NO Manufacturer's Name Type Diam. Model No. from ft. to from ft. to slot size Diam. slot size Gravel packed: NO Size of gravel gravel placed from ft. to ft. Material used in seal BENTONITE
Did any strata contain unusable water? NO
Type of water?
Method of cool Surface seal: YES Method of sealing strata off NONE ------(7) PUMP: Manufacturer's Name Type NONE ------(8) WATER LEVELS: Static level 85 ft. below top of well Date 10/23/99
Artesian Pressure lbs. per square inch Date
Artesian water controlled by NONE Land-surface elevation Work started 10/22/99 Completed 10/23/99 (9) WBLL TESTS: Drawdown is amount water level is lowered below static level.

Was a pump test made? NO If yes, by whom?

Yield: gal./min with ft. drawdown after hrs WELL CONSTRUCTOR CERTIFICATION: I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief. gal./min with Recovery data
Time Water Level Time Water Level Time Water Level NAME ȚILLIA WELL DRILLING (Person, firm, or corporation) (Type or print) ADDRESS 367 S BARR PORT ANGELES Date of test / / Bailer test gal/min. ft. drawdown after Air test 10 gal/min. w/ stem set at 93 ft. for 1 Artesian flow g.p.m. Date [SIGNED] hrs. License No. 0868

hrs.

Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? NO

Contractor's Registration No. TILLIWD043K0

Date 11/11/99

Or: 05/22/2000 At: 12:10 pm

Printed By: Dawn Merryman

Department of Ecology

(4610)

PO Box 5128

Lacey, WA 98509-5128

(360) 407-7095

FM 11 Date 05/23/2000

Receipt Name

BOURLAND, DONNA BOURLAND, WILLIAM

Current Document Number 461E1317CJ

Remitter Name

Check/Draw Number 9736

\$10.00 Document Amount

Method of Payment

Method of Payment Check
Comment Description WATER RIGHTS

2	/ar 3L	
	A dus	
	Sub	
	Prj Phs	
	Sub	
	Prj	
	Org	
	A	
	PIC	
	Work	
	Cnty	
	Sub	
	Maj Src	
	Maj Grp	
	Fund	
	~	
	⊢ O	
	Prgm	S

밀뉟

ln/ Ż

Ref Doc

Ref

\$10.00

Alloc

Sub Sid Cr

Sub Sid Dr

## RECORD OF SURVEY

URVEY OF TRACT 3, PER VOLUME 1 OF SURVEYS, PAGE 19, RECORDS OF CLALLAM COUNTY, LOCATED IN SECTION 3, TOWNSHIP 29 NORTH, RANGE 6 WEST, W.M., CLALLAM COUNTY, WASHINGTON



● SET 5/8" REBAR WITH PLASTIC SURVEY CAP STAMPED "NTI-SCOTT LS 23400" WITH PLASTIC GUARD STAKE. FOUND 1-1/4" IRON PIPE S33\*26'E, 3.65' FROM CALCULATED POSITION, NOT ACCEPTED.

② SET 5/8" REBAR WITH PLASTIC SURVEY CAP STAMPED "NTI-SCOTT LS 23400" WITH PLASTIC GUARD STAKE. FOUND 1-1/4" IRON PIPE S17\*30'E, 14.12' FROM CALCULATED POSITION, NOT ACCEPTED.

③ SET 5/8" REBAR WITH PLASTIC SURVEY CAP STAMPED "NTI-SCOTT LS 23400" WITH PLASTIC GUARD STAKE. FOUND 1-1/4" IRON PIPE S73\*54'E, 6.47' FROM CALCULATED POSITION, NOT ACCEPTED. APPARENTLY DISTURBED BY INSTALLATION OF UTILITIES.

• FOUND 1-1/4" IRON PIPE PER VOLUME 1 OF SURVEYS, PAGE 19, ACCEPTED. SET PLASTIC SURVEY CAP STAMPED "NTI-SCOTT" INSIDE TOP OF IRON PIPE.

SET PLASTIC SURVEY CAP STAMPED "NTI-SCOTT" INSIDE TOP OF IRON PIPE.

LINE MARKED WITH RED FLAGGING AND LATH MARKED "PROP. LINE".

(311.23' R) RECORD DISTANCE PER VOLUME: OF SURVEYS, PAGE 19, (TYPICAL).

THIS SUI TRAVERS. AND/OR INFRAREI WITH SO "EEL T. THE SUI TO EASE

EASEMEI EFFECT EXCEPT THIS RE EXISTINC TIONAL W.A.C. ( TIONAL FOR CL OWNERS

